

# G3 RAPID GRADE PASTE



#### **Product Name**

G3 Paste 400g

G3 Paste 1kg

G3 Paste 3kg

Standard G Mop Compounding Head 14mm

Advanced G Mop Fixed Head 14mm

Advanced G Mop Compounding Foam

Advanced G Mop Back Plate 14mm

Advanced G Mop Finishing Cloth 3pk

#### **Part Number**

G3-400/12

G3-1000/12

G3-3000/4

SGM-14/12

AGM-14/12

AGM-CF/12

AGM-BP14/6

FC-3/12

# **Product Description**

For use on OE & Refinish Medium Solids and Air Dried 2k paint systems (well cured).

#### **Directions For Use**

## For best results by machine follow these recommended steps:

- ∴ The surface should be clean and free from contamination such as abrasive paper particles or wax. Wipe with spirit wipe or degreasing agent if necessary.
- Farécla recommend the use of a hand-held polishing machine set to run at a free-running speed of approximately 1800 rpm when using Farécla G Mop 6" foams, or 1500rpm when using Farécla G Mop 8" foams.
- ☼ Before fitting the G Mop Compounding Foam to the polishing machine, soak it completely in clean water then squeeze out any excess.
- Fit the G Mop to the machine and spin the mop to one side to disperse the excess water. Care should be taken when using an electric machine to keep the water away from the machine.
- If the G Mop is already fitted to the machine it should be dampened thoroughly by adding clean water from a Farécla Water Spray Bottle to the centre of the white face of the foam.
- Apply a small quantity of G6 to the surface. Place the G Mop Compounding Foam face down on top of the compound, applying medium pressure, and start the machine.
- The G Mop should be moved steadily over the area to be rectified, ideally tilted at an angle of about 5-10 degrees to the surface. This ensures an even finish and prevents excessive localised heat.
- As the G6 breaks down a shine will begin to show through. Check that any abrasive paper marks have been removed. If not, apply more compound and repeat process.
- ☼ Once all the abrasive paper marks have been removed, ease off the pressure applied to the G Mop.
- To obtain the highest gloss, spray the surface with clean water and lightly polish the area again, this time with the G Mop flat on the surface (no further compound should be added).
- Finally wipe away any excess residue and buff using a Farécla Finishing Cloth to obtain a defect free, high gloss finish.

## **Key Features & Benefits**

- Removes P1500 abrasive marks quickly and easily Rapid cutting and no fillers Time saving and leaves a permanent finish.
- For an enhanced high gloss finish on dark colours, follow with G10 Extra Fine Grade Liquid Compound Two step process to an excellent finish no need to purchase other compounds.
- ⇒ Silicone free can be used in a bodyshop saves money, can be applied near to where paints are.